


LABORATORY TESTING INC. - 66,000 sq. ft. "Building 1" Main Facility



1st Floor

- 1 Shipping & Receiving Office
- 2 Magnetic Particle Inspection
- 3 Liquid Penetrant Testing
- 4 X-ray Inspection
- 5 Corrosion Testing
- 6 Future Machine Shop Expansion
- 7 EDM Machining
- 8 Sawing
- 9 Turning & Milling
- 10 Grinding & Polishing
- 11 Metallography Sample Preparation
- 12 Micro & Macro Exam, Microhardness
- 13 SEM/EDS Analysis
(14-16 see 2nd Floor Map below)
- 17 DT Order Entry, Specifications
- 18 Stress Rupture Testing
- 19 Elevated Temperature Tensile Testing
- 20 Hardness Testing
- 21 Tensile Testing
- 22 Charpy Impact Testing
- 23 600K Tensile Room
- 24 Quality Assurance

Building 1 2nd Floor

- 14 Instrumental Chemistry
- 15 Wet Chemistry
- 16 Training/Meeting Room
- 25 Sales/Customer Service, Marketing

Building 2

- Calibration
- Dimensional Inspection
- Fatigue & Fracture Toughness Testing
- Administration

Building 3

- Ultrasonic Testing
- Hydrostatic Pressure Testing

